



# BUILDING PRODUCT INFORMATION SHEET

## Class:

1 & 2

## Product Name

Telescopic Offset

## Product Description

Telescopic Offset - Various

Designed to ASNZS2918.2001

Material:

- 304 2b Stainless Steel

## Intended Use & Limitations

Intended for use in conjunction with a Foley Industries Flue Kit. On a domestic wood-burning fire appliances tested to ASNZS2918.2001.

Purpose: offset the vertical flue where the center to center is unknown.

Offsets and bends are higher-wear components. They should be placed in easier to access locations where possible to allow for replacement and visual inspection.

## Product Identifier

OSTESSXXXA45

## Place of Manufacture

New Zealand

## Manufacturer Name

Foley Industries Ltd

33 Bishop Dunn Place, Flat Bush, Auckland, New Zealand 2013

[www.foleyind.co.nz](http://www.foleyind.co.nz)

[equiries@foleyind.co.nz](mailto:equiries@foleyind.co.nz)

Phone: (09) 2744 766

NZBN: 9429039183958

## Servicing Information

Please contact your local NZHHA registered installer

Find a Service – NZHHA

[www.nzhha.co.nz/find-a-service](http://www.nzhha.co.nz/find-a-service)

## Relevant Building Code Clause

Durability: B2.3.1 (b) (i)

Telescopic Offset is designed and manufactured in accordance with ASNZS 2918. Telescopic Offsets have a durability of 5 years provided:

- The flue kit and appliance have been installed by a registered installer in compliance with ASNZS2918
- The flue kit has been annually swept and serviced
- Only natural untreated soft tree wood with less than 25% moisture content have been used as fuel in the appliance
- The appliance and flue kit is not modified in any way that is not compliant with ASNZS2918
- The environment is compliant with 2918 and material manufacture specifications
- The telescopic offset is not placed less than 1.2m from the top of the appliance.



## Installation Requirements

The flue kit, appliance and components have been installed by a registered installer in compliance with ASNZS2918

## Maintenance Requirements

The flue kit has been annually swept, serviced and inspected by a registered installer

## Is the Product Subject to Warning or Ban Under Section 26 of the Building Act 2004

N/A